



Interstate® Brick

a division of PABCO Building Products, LLC

9780 South 5200 West
West Jordan, Utah 84088-5625
(801) 280-5230
(800) 233-8654
Fax (801) 282-5245

M/049/002*
M/049/030

December 27, 2005

Susan M. White
Mine Program Coordinator
Mineral Regulatory Program
State of Utah
Department of Natural Resources
Division of Oil Gas and Mining

Dear Ms. White:

Please find attached three maps that are the response to two letters from DOGM dated Oct. 26 concerning the five-year review of Reclamation Surety estimates at M/049/002 (Smokey Joe Mine) and M/049/030 (Snow White Mine).

A copy each of the Reclamation Treatments map and Surface Facilities map that were recently submitted as part of a Large Mine Plan are included for M/049/030. No activity has taken place since these maps were made. Hopefully these will be sufficient for this request.

Although there was seeding that took place at the Snow White mine in the fall of 2005, at this time a form MR-Bond-Release is not being submitted, but it is our intention to submit one for this work.

Sincerely,

John Hewitt
Assistant Plant Manager
Interstate Brick

PABCO BUILDING PRODUCTS, LLC. BRICK DIVISION

H.C. MUDDOX: 4875 Bradshaw Road, Sacramento, CA 95827-9727

INTERSTATE BRICK: 9780 South 5200 West, West Jordan, Utah 84088-5625

RECEIVED

DEC 27 2005

DIV. OF OIL, GAS & MINING

notes:
these do not exist at this mine:
stationary buildings
stationary mining processing equipment
utilities
drainage structures (berms, culverts, etc.)
solid or liquid waste containment areas

colored lines show direction and view of pictures

RECEIVED

DEC 27 2005

DIV. OF OIL, GAS & MINING

5. Legend



- overburden / rock piles
- access road to mine from solders pass road
- terracing and roads
- disturbed area boundary - 10.8 acres
- mine floor and stockpile pad area

X Prospect

X Prospect


Shaypit

5616



0 25 50 100 150 200 Meters

0 100 200 400 600 800 Feet



Interstate Brick
a division of F&B Building Products, LLC

Interstate Brick
M049.002
Smokey Joe Mine as of December 2005

Map requested by D OGM for 5 year bond review

shown on USGS Solders Pass Topo Map
T7S, R1W, SW1/4 Sec. 9, SLBM
12/05, JH